

Loads

- driver turning ^{steering} wheel full-steer and wheel bumps smth
- driver pushing into steering wheel
- full-steer no wheel turn
- maybe slanted from tie rod?

Overrun of tie rods

- bump-steer: and the wheel turns when you bump into smth (want to minimize)
 - when driver tries to hold wheel straight when bumping into smth
 - puts tie rods in compression and yikes
 - force goes into tie rods rather than steering rack
 - since this yr we fixed the tie rod issue, now the loads will go into the steering rack so steering rack likely to fail
- tie rod is 1st pt of constraint
 - w/o it, the wheel would be floppy
 - another mode for force to transfer through
 - lots of force goes through it bc of that

FEA Setup

- full-steer
 - bush bushing against axis
 - wheel bumps smth
- apply load
- constrain part
- screw forces
 - bolt pretension
- bearing friction
 - allows rotation
- bob1 - T6 (not bob1 Alloy) → remember to check material
- rule of thumb: 3 nodes on 2 face
- run Study
 - stress
 - disp
 - strain
 - FOS
- should def run assembly FEA
 - rule supports housing, too!

Material

- usually run to deflection (not to failure)

FEA

- static
- transient - ~~static~~ ^{structural}
- FEA over time (moving-ish)
- good for large assemblies (large displacement)


$$- FOS = \frac{\text{max stress}}{\text{work/design stress}}$$

- at every nodes, there's a certain amount of stress
- $FOS < 1$ means work/design stress is bigger than max stress so yield

- rigid-body

- solve a free-body diagram?
- what are the resultant forces?
- Limit applied force to wheel and from the analysis give the forces seen at each joint
- basically the resulting force "transmitted" due to constraints
- this is what meshes are


→ either run assembly wrong or design sucks



- each coordinate system is a set of load cases at a joint
- each node is a coord system

How WFT collected Data

- relative to hub free
- therefore z-axis rotation isn't exact?
- M_z is steering (wheel turning) but isn't actual rotation of the hub, it's offset
- M_z is important bc it's the amt of load transferred to tie rod
- there's a transfer of loads from wheel to steering axis
- the forces must be same



Action Items from 12/31/23

✓ open Front Inboard Assembly

✓ CAD blocks that support entire clamp of housing

✓ cutout in middle for weight reduction?

→ does that affect support for clamp?

✓ find bolts on McMaster

→ button head (bigger head ϕ) or socket head (smaller head ϕ)?

→ non-loc hole ϕ is 0.307" so maybe 0.375" is 2 bit close

→ should be 1.75" long according to internet, or at least

two threads protrude


✓ washers on non-locating bolt holes

→ literally only one washer on McMaster works bc of limited OD





✓ find nuts that fit

✓ CAD small piece that keeps nuts from rotating

✓ return ~~to~~ assembly w/ v2K (turn 1/1/24)




rule of clamp support...





- nut turns out they literally welded a nut onto a tab which makes things a lot easier
→ it's a McMaster part (93560A140)

1/3/24



- nuta again!

yaymie 01/01/2024 19:46
so we had a tab with cutouts for the nut and it was welded onto the other tab
so like double layer thickness tab
if you look at the steering rack tabs from last year, you might see it



CAD

Questions

- Why are the corners filleted on the housing clamps?

→ pub stress conc

- How do you determine mesh size systematically? or do you literally just guess?

- How do you determine screw size systematically?

- Does meshing w/ mesh controls stick?

→ ex) making out file in normal mesh and fine again for a certain face

- Pillow block material? C63000?

→ through harden or carburize harden

FEA Setup w/ Assembly

- Ammiris (Full-steer No-turn)

→ Force thru the rod so upward angled on rack ^{force}

- walk through

→ don't cut: clevis, bearing, cam (exclude these in part)

→ cut: rack and housing → bc don't need to complicate to full extent

→ local interactions

→ type

→ blue box: where force is coming from

→ pink: where rest

→ set to really coarse first time to see if runs which tells you if fixtures are good

→ then make finer on md on until adequate mesh to define stress concentration

FEA

- Daniel's realization





→ pillow block like shoulder is "perfectly square" so SW doesn't know what to do w/ it?

- basically the stress conc will prob be less severe the finer the mesh is?

→ concluded from limited experience, cut really confirm bc Liam said "that's the fun of it"

→ maybe Ammiris knows?

added slight fillet but almost
↑ do nothing



Heat Treating (Daniel's overview)

- different for core and shell?

- types

→ through?

→ core and surface hardened so very brittle (inelastic), breaks easily when deformed

→ good for tension cases

↳ 2ks
compressed

→ carbonized

→ only surface hardened so doesn't break as easily when deformed (elastic)

→ good for compression cases

Optimizing Pillow Block and Pillow Block Shoulder FOS



1/15/24

- previous min FOS on shoulder: 0.41
- change material to C30000 (not C63000)

	SPH	PB	SPH	PB	SPH	PB	SPH	PB
	0.15	0.0365	0.125	0.0615	0.1125	0.074	0.10025	0.08025
min FOS	0.82	0.09563	0.86	0.1312	0.92	0.1391	0.95	0.1486

Daniel's Enlightenment

1/22/24



MIN FOS 0.2932!!
!!!

(previously 0.1486)

1/24/24

- forgot to size dimensions so min FOS is not as high as 0.2932 anymore

- need to figure out geometry behind maximizing FOS

New Procedure..

- suppress hole



→ no more pillow block

→ add extrusion^{in SPH} to contact steering roll




- circle pillow block...




→ might not be the most accurate bc tolerances



← wasn't able to run FEA (syntax wrong w/ interactions...)



- multiple pts of contact (> 2)



multiple pts of contact (not possible, no endmill small enough)

To-Do


- figure out pillow block/housing design

- FEA for full-steer wheel bump

- review machinability w/ jitter


1/25/24

Setup overview w/ 1m


- realized a contact interaction was missing btwn bottom of pillow block and top of SPH shoulder
- no wonder why the rock was bending out of its mind like this: 
- added interaction and results made a little more sense (low FOS on block)

Tolerancing Brass Bushing and Housing



- check Machinery Handbook
- different types of fits explained
- in this case, press fit (FN?)
- ↳ need enough friction force to keep bushings in place



FEA Overview w/ Xviewer


- nodes  need an opposing force for static sim
- $dx = 0$ (boundary of 0 mount)

nodes near each other on parts "connect" through local interactions



- one solution: increase pillow block SA bc same force over more area
- 0.18 FOS on pillow block... etc

triled... (.000")



- probably triled bc inadequate fixtures... 2/1/24
- changed bearing supports to fixed hinges...

lets try smth new!

- increase depth of pillow block (increase fillet radius)


→ V/PPEE! 0.5b min FOJ

→ Daniel reminded me that the 120° version still exists and that I should try that again

→ I don't exactly remember why I stopped testing that one

→ either be hard to machine to tolerance (what I wrote down above) or the sim failed

120° version



It just doesn't solve...

2/5/24

- one of the loads, fixtures, interactions, or connections are just wrong

→ but, when I run the ex20t some

sim w/ the flat pillow block, it

solves...

THAT'S IT. I'm going to ask ANSYS on this...

THAT'S IT. We'll just remove it. No more FEAs!

2/5/24

NEVERMIND. More FEAs (Jaffer)

2/6/24

- need to validate pinions themselves (they're already sent though...)

$$\frac{\text{force}}{\text{mm}} = \frac{1200 \text{ in lb}}{1.21 \text{ (pitch circle)}} \cdot \frac{1}{2}$$

(apply to force of steering rack tooth)

$$r = rF \sin \theta$$


- add 5mm gap between pillow block (!!!)

→ bc rack might not be operating yet

!!! unhh...

→ min FOS went down on EVERYTHING

→ decreased pillow block height by 5 thou



- rack FEA w/ Ammm

→ sim w/ pillow block

→ split lines for hatching (or just returning part in drawings)

→ center of rack force

→ load: from ergo testing

→ 60 lbf from Benchmark (NOT WFT data!)

→ remember to fix table everything! otherwise sim no run!


→ running

→ 1st time, min FOS was mid (-10 thou?)

→ 2nd time, tried w/ short PB

2nd realized rack was displacing

in the opposite of expected direction



→ run it again and checked deformation w/ pinion

→ saw that pinion was spinning CCW instead of CW so basically we run the sim entirely incorrectly

→ reversed the load to be CW

→ sim doesn't solve

→ "model may not have adequate fixtures"

→ used "Underconstrained Bodies" to check, but it calculated that the model is fully constrained so...

→ it seems like there are adequate fixtures...

→ rack stays still:

→ axially

→ ~~rotationally~~ radially

→ ~~rotationally~~

→ ~~rotationally~~ circumferentially? ~~rotationally~~...